

PRIORITY 1

OUT52068

SECRET 151949Z

25X1

16 OCT 1963

1. CAMERA B 11 WAS USED IN MISSION 3749 FLOWN ON 13 OCTOBER 1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE, THE RESOLUTION IS GOOD.

B. 9R SIDE: ALL POSITION INDICATOR LIGHTS WERE INOPERATIVE EXCEPT FOR 3R, 1R AND 3L. THE LATTER WERE VERY FAINT. PLUS DENSITY DOTS CAUSED BY STATIC ARE PRESENT INTERMITTENTLY FROM FRAME 001 TO 795.

HFS TIG
CJS /
CFC /
PMS /

Grace (File)

C. 9L SIDE: MINUS DENSITY DOTS 1.55" APART AND PARALLEL TO THE MAJOR AXIS OCCUR 0.5", 5.5" AND 5.7" FROM THE INBOARD EDGE FROM FRAME 005 TO 133. THE SAME TYPE OF DOTS APPEAR 2.5" FROM THE INBOARD EDGE FROM FRAME 005 TO 338. PLUS DENSITY STREAKS ARE PRESENT IN THE FIRST 800 FRAMES. ALL THE POSITION INDICATOR LIGHTS ARE INOPERATIVE THROUGHOUT THE MISSION.

D. BOTH SIDES: A MINUS DENSITY STREAK OCCURS INTERMITTENTLY 0.1" FROM THE INBOARD EDGE OF EACH SIDE. THERE IS ALSO INTERMITTENT EDGE FOG ALONG THE INBOARD EDGE OF EACH SIDE THROUGHOUT THE MISSION. THE LAST TITLED FRAME ON EACH SIDE IS 2489.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS OTHER THAN MENTIONED ABOVE.

Declassification Review by NGA/DoD

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING OF THE POSITIVE IS GOOD.

Excluded from automatic
downgrading and
declassification

SECRET

C. CLOUDS AND HAZE DEGRADED OR OBSCURED 35 PER CENT OF
THE MISSION.

S E C R E T

END OF MESSAGE

1